


## Spider Alert

In some areas of the country, spiders or small insects have been found to create “FLASHBACK” problems. The spiders spin webs, build nests and lay eggs in the grill’s venturi tube(s). This obstructs the full flow of gas to the burner. Some gas backs up and can result in a “flashback” –a fire in the venturi behind the control panel.

The burner and venturi assembly should be removed from the grill and cleaned after a grill has set idle for an extended period.



**IF YOU NOTICE THAT YOUR GRILL IS GETTING HARD TO LIGHT OR THE FLAME ISN'T AS STRONG AS YOU THINK IT SHOULD BE, TAKE THE TIME TO CHECK AND CLEAN THE VENTURI(S).**

